
ABS Warning Light Remains ON

DESCRIPTION

If any of the following is detected, the ABS warning light remains ON.

- 1. The skid control ECU connectors are disconnected from the skid control ECU.
- 2. There is a malfunction in the skid control ECU internal circuit.
- 3. There is an open in the harness between the combination meter and skid control ECU.

WIRING DIAGRAM




INSPECTION PROCEDURE

NOTICE:

When replacing the master cylinder solenoid, perform zero point calibration (See page BC-24).

1	CHECK DTC		



(a) Check the combination meter system (See page ME-15). **OK:**

Combination meter is normal.



REPLACE COMBINATION METER



REPLACE MASTER CYLINDER SOLENOID