



## INSTALLATION

- 1. INSTALL INTEGRATION CONTROL AND PANEL ASSEMBLY**
  - (a) Connect the 3 connectors.
  - (b) Engage the 4 clips and install the integration control assembly.
  - (c) Install the 2 screws.
- 2. INSTALL INSTRUMENT PANEL GARNISH LH (See page [IP-33](#))**
- 3. INSTALL INSTRUMENT PANEL GARNISH RH (See page [IP-33](#))**
- 4. CONNECT CABLE TO NEGATIVE BATTERY TERMINAL**  
Torque: 3.9 N\*m (40 kgf\*cm, 35 in.\*lbf)